



03500.017582

PATENT

COFC

SA

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:

TAKATERU OKUBO

Appl. No.: 10/667,352

Filed: September 23, 2003

For: IMAGE FORMING APPARATUS WITH
FIXING APPARATUS AND CONVEYING
ROLLERS DOWNSTREAM OF THE FIXING
APPARATUS, THE CONVEYING ROLLERS
HAVING A PORTION WITH A RELEASING
LAYER

U.S. Patent No.: 6,909,873 B2

Issued: June 21, 2005

) : Examiner: Quana M. Grainger
): Group Art Unit: 2852
): Confirmation No.: 3391
):
):
):
):
):
):
):
):
): September 16, 2005

**Certificate
SEP 22 2005
of Correction**

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentee's undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Lawrence A. Stahl
Attorney for Patentee
Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIMLINE

PATENT NO. : 6,909,873 B2

DATED : June 21, 2005

INVENTOR(S) : TAKATERU OKUBO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [54] TITLE:

Line 4, "APPARATUS." should read --APPARATUS,--.

COLUMN 1:

Line 4, "APPARATUS." should read --APPARATUS,--.

COLUMN 8:

Line 44, "father" should read --farther--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,909,873 B2

No. of add'l. copies
@ 30¢ per page

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : 6,909,873 B2

DATED : June 21, 2005

INVENTOR(S) : TAKATERU OKUBO

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COVER PAGE AT ITEM [54] TITLE:

Line 4, "APPARATUS." should read --APPARATUS,--.

COLUMN 1:

Line 4, "APPARATUS." should read --APPARATUS,--.

COLUMN 8:

Line 44, "father" should read --farther--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,909,873 B2

No. of add'l. copies
@ 30¢ per page